






- | | | | | | |
|------------------|------------------|----------|-----------------|------------------|-------------------|
| 7
6x36
x12 | 2
x1 | 3
x4 | 4
3x25
x4 | 5
x4 | 6
3,5x16
x8 |
| x4 | 8
3x16
x16 | 9
x4 | 10
x50 | 11
4x20
x8 | 12
x20 |
| 13
x2 | 14
3x45
x2 | 15
x2 | 16
x12 | | |

Czas mont. - 50 min.





- | | |
|----------|---------|
| 12
x4 | 3
x4 |
|----------|---------|




- | |
|-----------------|
| 8
3x16
x8 |
|-----------------|

- | |
|---------|
| 7
x4 |
|---------|



- | |
|-----------------|
| 4
3x25
x4 |
|-----------------|

- | |
|----------|
| 15
x2 |
|----------|





4

5

6

6 3,5x16
x4(x2)





14 3x45
x1(x2)

13
x1(x2)

8 3x16
4 (x2)



9
2 (x2)

7






16
x12

8



11 4x20
x4(x2)

9



10
x 50

