





PRIMO

PWT50




16.5.2017

- (D)** Montageanleitung
- (FR)** Notice de montage
- (NL)** Handleiding voor de montage
- (CZ)** Montážní návod
- (HU)** Szerelési útmutató
- (TR)** Montaj talimatı
- (GB)** Assembly Instructions
- (IT)** Istruzioni di montaggio
- (PL)** Instrukcja montażu
- (SK)** Návod na montáž
- (RO)** Instrucțiunile de montaj
- (RU)** Инструкции по монтажу





20 min.




1






NA 4x13 x9	C x20	Z x20	N 3x20 x8	X x1	M M4x22 x1	W3 x1	ZA x1	TB x1
B x20	A 8x32 x20	H 5,3x13 x8	R x4	PC x14	HD x8	NC 4x16 x6	NGD x4	TA x1
						ZD x6	Z x6	






2



3






4





5


M M4x22 x1	W3 x1
NA 4x13 x8	ZD x6
PC x4	NC 4x16 x6






C x4	Z x4
----------------	----------------





C x8	Z x8
----------------	----------------





9





11



10



12



13

